

## Crediton

| Play Area               | Number of survey responses | Condition survey October 2015   | Legal restrictions relating to site                           | Recommendation to PDG/Cabinet   | Estimated decommission cost for site | Potential savings in 2016/2017 |
|-------------------------|----------------------------|---|---|---|--------------------------------------|--------------------------------|
| Greenway                | 4                          | This play area is un-equipped, the safety surface remains and the boundary fence requires repair.         | No relevant restrictions                                      | To decommission the site and to reassign from a play area to a public open space. To lease the land to Crediton Town Council.                         | £1,500                               | £799.25                        |
| Queen Elizabeth Drive 2 | 0                          | This play area is un-equipped and consists of a small grassed area and a shrub bed.                       | Cannot be used other than as a public open space or play area | To reassign from a play area to a public open space and to lease the land to Crediton Town Council. This site has never been equipped since adoption. | £0                                   | £221.22                        |
| Beech Park              | 28                         | The two sets of swings will require painting in the near future and the safety tiles have gaps appearing. | No relevant restrictions                                      | This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.                             | £0                                   | £0                             |
| Fulda Crescent          | 6                          | This play area has a tarmac surface and is un-equipped.   | No relevant restrictions                                      | To reassign from a play area to a public open space. To lease the land to Crediton Town Council.  | £0                                   | £411.22                        |
|                         |                            |   |   | <b>Totals</b>   | <b>£1500</b>                         | <b>£1431.69</b>                |

## Cullompton

| Play Area      | Number of survey responses | Condition survey October 2015  | Legal restrictions relating to site | Recommendation to PDG/Cabinet  | Estimated decommission Cost for site | Potential savings in 2016/2017 |
|----------------|----------------------------|--|-------------------------------------|--|--------------------------------------|--------------------------------|
| Head Weir Road | 92                         | The equipment and safety surface is over 20 years old and is in need of replacement.   | No relevant restrictions            | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0                                   | £0                             |
| Conifer Close  | 7                          | The spring mobile is in a satisfactory condition and the climbing frame needs replacement.   | No relevant restrictions            | <b>To close the play area and to dispose of the land. Linden Road play area is 200m distance.</b>                                | £1,500                               | £411.22                        |
| Ash Drive      | 7                          | The two spring mobiles and safety surface are in satisfactory condition.   | No relevant restrictions            | <b>To close the play area and to dispose of the land. Linden Road play area is 250m distance.</b>                                | £1,500                               | £411.22                        |
| Tufty Park     | 106                        | The wooden climbing frame and the set of swings will require removal within the next 12 months. The metal multi-play unit and the 2 spring mobiles are in satisfactory condition. Some of the safety surfacing requires repair and the tarmac path also requires repair. | No relevant restrictions            | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0                                   | £0                             |

## Annex 2

|                 |    |   |   |  |              |                 |
|-----------------|----|---|---|--|--------------|-----------------|
| Clover Drive    | 13 | The metal multi-play frame is in a poor condition, the surfacing and fence is satisfactory. | Cannot be used other than a public open space or play area. | <b>To close the play area and to re-assign as a public open space. Spindlebury play area is within 100m distance.</b>            | £2,000       | £411.22         |
| Spindlebury     | 5  | The swings, balance beam and burma bridge are all satisfactory.                             | Cannot be used other than a public open space or play area. | <b>To leave this site as a play area.</b>  | £0           | £0              |
| Siskin Chase    | 10 | The swing and multi-play unit are all in a satisfactory condition.                          | Cannot be used other than a public open space or play area. | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0           | £0              |
| Dove Close      | 9  | The slide and swing are in a satisfactory condition.  | Cannot be used other than a public open space or play area. | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0           | £0              |
| Chaffinch Drive | 12 | The multi play unit and swing are in a satisfactory condition.                              | Cannot be used other than a public open space or play area. | <b>To leave this site as a play area.</b>  | £0           | £0              |
| Starlings Roost | 9  | The swing, igloo climber and slide are all in a satisfactory condition.                     | Cannot be used other than a public open space or play area. | <b>To leave this site as a play area.</b>  | £0           | £0              |
|                 |    |   |   | <b>Totals</b>  | <b>£5000</b> | <b>£1233.66</b> |

## Tiverton

| Play Area     | Number of survey responses | Condition survey October 2015   | Legal restrictions relating to site                         | Recommendation to PDG/Cabinet  | Estimated decommission Cost for site | Potential savings in 2016/2017 |
|---------------|----------------------------|---|---|--|--------------------------------------|--------------------------------|
| Coles Mead    | 6                          | The igloo climber is in poor condition, the slide is satisfactory and the safety surface needs replacing.   | No relevant restrictions                                    | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b>     | £0                                   | £0                             |
| Priory Road   | 7                          | The multi-play unit and swings are in satisfactory condition, the surface requires repair.  | Cannot be used other than a public open space or play area. | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b>     | £0                                   | £0                             |
| Halsbury Road | 4                          | The multi-play unit is in a poor condition and has to be removed, the safety surface and fencing is in a satisfactory condition. This site is currently closed. | Cannot be used other than a public open space or play area. | <b>To close the play area and to re-assign as a public open space. Wilcombe play area is approximately 5 minutes' walk.</b>          | £1500                                | £411.22                        |
| Hawthorn Road | 20                         | The swings and see-saw are in a satisfactory condition.   | No relevant restrictions                                    | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b>     | £0                                   | £0                             |
| Trickey Close | 9                          | The spring mobile is in a poor condition, the swings, multi-play unit are in a satisfactory condition.  | No relevant restrictions                                    | <b>For this site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0                                   | £0                             |
|               |                            |   |   | <b>Totals</b>  | <b>£1500</b>                         | <b>£411.22</b>                 |

**Bow**

| <b>Play Area</b> | <b>Number of survey responses</b> | <b>Condition survey October 2015</b>   | <b>Legal restrictions relating to site</b>                  | <b>Recommendation to PDG/Cabinet</b>   | <b>Estimated decommission Cost for site</b> | <b>Potential savings in 2016/2017</b> |
|------------------|-----------------------------------|--|---|--|---|---------------------------------------|
| Godfrey Gardens  | 9                                 | The spring mobile, fencing and safety surface is in a satisfactory condition               | Cannot be used other than a public open space or play area. | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0  | £0                                    |
| St Martins Close | 6                                 | The multi play unit and safety surface is in a poor condition the fencing is satisfactory. | Cannot be used other than a public open space or play area. | <b>To close the play area and to re-assign as a public open space. lter Park play area is 120m away.</b>                         | £1500                                       | £411.22                               |
|                  |                                   |  |   | <b>Totals</b>  | <b>£1500</b>                                | <b>£411.22</b>                        |

**Copplestone**

| <b>Play Area</b> | <b>Number of survey responses</b> | <b>Condition survey October 2015</b>   | <b>Legal restrictions relating to site</b>                  | <b>Recommendation to PDG/Cabinet</b>   | <b>Estimated decommission Cost for site</b> | <b>Potential savings in 2016/2017</b> |
|------------------|-----------------------------------|--|---|--|---|---------------------------------------|
| Fernworthy Park  | 12                                | The multi-play unit and spring mobile are in a satisfactory condition, the safety surface shall soon require replacing | Cannot be used other than a public open space or play area. | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0  | £0                                    |
|                  |                                   |  |   | <b>Totals</b>  | <b>£0.00</b>                                | <b>£0.00</b>                          |

### Morichard Bishop

| Play Area | Number of survey responses | Condition survey October 2015   | Legal restrictions relating to site | Recommendation to PDG/Cabinet  | Estimated decommission Cost for site | Potential savings in 2016/2017 |
|-----------|----------------------------|---|-------------------------------------|--|--------------------------------------|--------------------------------|
| Greenaway | 3                          | The slide is in a poor condition the swings and surfacing are satisfactory. | No relevant restrictions            | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0                                   | £0                             |
|           |                            |   |                                     | <b>Totals</b>  | <b>£0.00</b>                         | <b>£0.00</b>                   |

### Uffculme

| Play Area  | Number of survey responses | Condition survey October 2015   | Legal restrictions relating to site                               | Recommendation to PDG/Cabinet  | Estimated decommission Cost for site | Potential savings in 2016/2017 |
|------------|----------------------------|---|---|--|--------------------------------------|--------------------------------|
| Pathfields | 29                         | The multi-play unit, swings stepping stones, fence and safety surface are in a poor condition. The site requires refurbishment. | Cannot be used other than a public open space (POS) or play area. | <b>To accept the Parish Council's offer of funding, details to be decided. If no adequate funding available manage decline to provide public open space.</b> | £0                                   | £589.24                        |
|            |                            |   |   | <b>Totals</b>  | <b>£0.00</b>                         | <b>£589.24</b>                 |

## Willand

| Play Area          | Number of survey responses | Condition survey October 2015  | Legal restrictions relating to site                         | Recommendation to PDG/Cabinet  | Estimated decommission Cost for site | Potential savings in 2016/2017 |
|--------------------|----------------------------|--|---|--|--------------------------------------|--------------------------------|
| Chestnut Drive     | 16                         | The multi-play unit and swings are in a poor condition and need refurbishment. | Cannot be used other than a public open space or play area. | <b>This site to continue as a play area until such times that the equipment is beyond economic repair and has to be removed.</b> | £0                                   | £0                             |
| Mallow Court       | 13                         | The multi-play unit, swing and spring mobile are in a satisfactory condition.  | Cannot be used other than a public open space or play area. | <b>To allow the Parish Council to take control of play area subject to further negotiations with the parish council.</b>         | £0                                   | £487.56                        |
| Worcester Crescent | 29                         | The multi-play unit, see-saw and swing are in a satisfactory condition.        | Cannot be used other than a public open space or play area. | <b>To allow the Parish Council to take control of play area subject to further negotiations with the parish council.</b>         | £0                                   | £812.94                        |
|                    |                            |  |   | <b>Totals</b>  | <b>£0.0</b>                          | <b>£1300.50</b>                |
|                    |                            |  |   |  |                                      |                                |
|                    |                            |  |   | <b>Grand Total</b>   | <b>£9500</b>                         | <b>£5377.53</b>                |