## **Economy PDG Risk Management Report - Appendix 2**

## Report for 2016-2017 For Economy - Cllr Richard Chesterton Portfolio Filtered by Flag:Include: \* CRR 5+ / 15+ For MDDC - Services Not Including Risk Child Projects records or Mitigating Action records

Key to Performance Status:Risks: No Data (0+)High (15+)Medium (5+)Low (1+)

## **Economy PDG Risk Management Report - Appendix 2**

**<u>Risk: Pannier market general risk assessment</u>** General risk assessment for the market's day to day operation

**Effects (Impact/Severity):** Score of 5 as their appears to be a movement in the structure causing the glass doors to bow

Causes (Likelihood): Unclear structural survey required

Service: Pannier Market

<b>Current Status: Medium</b>	Current Risk Severity: 4 -	Current Risk Likelihood: 3 -
(12)	High	Medium

Head of Service: None

**Review Note:** A structural survey has been done we still need to identify the cause of the bow in some of the glass doors but they are not load bearing and are made of toughened glass which beads when shattered.

Printed by: Catherine Yandle

SPAR.net

Print Date: 09 November 2016 10:08